



Your Reliable and Trustworthy Surplus Equipment Market Partner... Worldwide

Advantest T5503A Test System (JAD-37294)

Make: Advantest
Model: T5503A
Quantity: 1
Vintage: 2011
Inspection: Yes

Configuration:

```
SYSTEM:System_name          T5503A
SYSTEM:Each_machine_name
SYSTEM:AC_power_line_frequency 60
SITE:Site_configuration     1
TH:Type                     3840CH
//PE                        1 7 13 65 71 77
TH:SITE1_Pe_configuration_A 1 1 1 9 9 9
TH:SITE1_Pe_configuration_C 0 0 0 0 0 0
TH:SITE2_Pe_configuration_A 0 0 0 0 0 0
TH:SITE2_Pe_configuration_C 0 0 0 0 0 0
//DCPPS 1 2 3 4
DPU:SITE1_DcPps_configuration 1 0 0 0
DPU:SITE2_DcPps_configuration 0 0 0 0
```

BOARDNAME/REVISION LIST

PRINT OUT AT 2011/06/27 13:23:04

UNIT NAME << EWS >>

SLOT	BOARDNAME	REV	DATE
1	WUN-H3610295EWS	ACA	2011/06/14 14:37:20

UNIT NAME << TPU >>

SLOT	BOARDNAME	REV	DATE
1	WUN-H3610248SITEC	ADC	2011/06/14 14:37:20
2	BPC-035232	AHA	2011/06/14 12:29:25
3	WUN-H3610248SITEC	ADC	2011/06/14 14:37:20
4	BPC-035232	AHA	2011/06/14 12:29:25

JAD Group, Inc,
www.jadgrp.com

888 E. Belvidere RD, Suite 213 Grayslake, IL 60030 USA
Telephone: +1-847-223-1804

UNIT NAME << AIR >>

SLOT	BOARDNAME	REV	DATE
1	BPG-034374	BCB	2010/07/26 09:25:32

UNIT NAME << SYSMONI >>

SLOT	BOARDNAME	REV	DATE
1	BPR-035356	BEA	2011/06/14 12:29:25

UNIT NAME << CLUNT >>

SLOT	BOARDNAME	REV	DATE
1	KH3-910150	LND	2010/07/26 09:25:32

UNIT NAME << THU >>

SLOT	BOARDNAME	REV	DATE
1	BPS-035357X02	BAC	2011/06/23 17:49:52
2	BPS-035357X02	BAC	2011/06/23 17:49:52
3	BPS-035357X02	BAC	2011/06/23 17:49:52
4	BPS-035270	CFA	2011/06/14 12:29:25
5	BPS-035361	AHA	2011/06/14 12:29:25
6	BPS-035361	AHA	2011/06/14 12:29:25
7	BPS-035361	AHA	2011/06/14 12:29:25
8	BPN-035362	AAA	2011/06/14 14:36:47
9	BPS-035358	EEB 2	011/06/23 17:49:52
10	BPS-035357X02		2010/08/26 18:55:52
11	BPS-035357X02		2010/08/26 18:55:52
12	BPS-035357X02		2010/08/26 18:55:52
13	BPN-035362	AAA	2011/06/14 14:36:47
14	BPS-035357X02		2010/08/26 18:55:52
15	BPS-035357X02		2010/08/26 18:55:52
16	BPS-035357X02		2010/08/26 18:55:52
17	BPS-035270		2010/08/26 18:55:52
18	BPS-035357X02		2010/08/26 18:55:52
19	BPS-035357X02		2010/08/26 18:55:52
20	BPS-035357X02		2010/08/26 18:55:52
21	BPN-035362	AAA	2011/06/14 14:36:47
22	BPS-035357X02		2010/08/26 18:55:52
23	BPS-035357X02		2010/08/26 18:55:52
24	BPS-035357X02		2010/08/26 18:55:52
25	BPS-035270		2010/08/26 18:55:52
26	BPS-035358	EEB	2011/06/23 17:49:52
27	BPS-035357X02		2010/08/26 18:55:52
28	BPS-035357X02		2010/08/26 18:55:52
29	BPS-035357X02		2010/08/26 18:55:52
30	BPN-035362	AAA	2011/06/14 14:36:47

31	BPS-035357X02		2010/08/26 18:55:52
32	BPS-035357X02		2010/08/26 18:55:52
33	BPS-035357X02		2010/08/26 18:55:52
34	BPS-035270		2010/08/26 18:55:52
35	BPL-035359	AFA	2011/06/14 12:29:25
36	KH3-010182	---	2010/07/26 09:25:32
37	KH3-010182	---	2010/07/26 09:25:32

Note 1: Mother Board Part number KH7-010306, KH7-010307

Note 2: System includes Diagnostic and Calibration boards.

Photos:





